

RADON IN THE WORKPLACE

Road to Compliance for Employers

01 Identify

All employers should identify whether their workplace building is located within an area where high indoor radon levels are likely to occur. Indicative maps are available in most countries



03 Mitigate

If the radon level is measured above the national radon concentration limit, mitigation systems can be installed by specialised professionals to reduce the radon level



02 Test

Where the building is in an area of increased risk, radon testing using an approved method should be carried out in the building



04 Manage

In the less common cases in which the radon levels cannot be reduced, restricting access to the area and monitoring workers will be the solution



05 Review

The radon level should be re-measured at regular intervals as any changes to the building (e.g. new windows) or changes to the use of a building, will change the radon levels in the indoor air

